Went to site of gravel pit at intersection of Mayflower & 23. There has accumulated at least 200 metal barrels with various labels, some with gunshot holes in them, others turned on side with tops open.

Oil and sludge was flowing in all directions on surface and at one point an excavated area had a pool of oil, sludge and water several inches deep.

Following that visit we went to the site of the South Bend Freight Lines fill at Gertrude Street. There is a pool of stagnant water with putressible material, paper, lumber stacked on bank extending into water. Autos, truck bodies and other material of all types extend over several acres. This is the site proposed for a landfill by Schulman's. On site evaluation does not appear to offer an area for excavation and fill without getting into ground water.

Others on visit: Cal, Pete, Louis K.

BI

der 10, 1970.

Callet Who Suly Secriting findings, and, conspected the HV I should next set if entired agrainal.

EPA Region 5 Records Ctr.

301531